


## Inverter efficiency

This chart shows the Inverter efficiency. As can be seen most of the torque speed envelope the efficiency is over 92% and quite a bit at 96 - 98%.



The second chart shows the difference in torque between what is asked for in software and what you actually get.

As we can see from the chart this is mostly less than 0.2Nm error.

